## **EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
LI	503	((sensor sens\$4 detect\$4) and (fail\$4 faul\$4 malfunctio\$4) and (headlight head-light headlamp head-lamp)) and compensat\$4 and turn\$3 and left and right	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/28 08:19
L2	284	l1 and @ad<"20030131"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/28 08:20
L3	120	((sensor sens\$4 detect\$4) same (fail\$4 faul\$4 malfunctio\$4) same (headlight head-light headlamp head-lamp)) and (vehic\$4 automob\$5) and (turn\$4 bend\$4) and left and right	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/28 08:28
L4	1	((sensor sens\$4 detect\$4) and (fail\$4 faul\$4 malfunctio\$4) and (headlight head-light headlamp head-lamp) and pivot and left and right and unit and compensating).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/28 08:31
S15 28	17	"5400540"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 14:28
S15 29	161	surefire	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 14:39
S15 30	473	362/464.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 15:04
S15 31	884	362/523-532.ccls. and (headlight head-light headlamp head-lamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 15:56
\$15 32	60	362/240.ccls. and (headlight head-light headlamp head-lamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/02/27 15:32
S15 33	42	362/250.ccls. and (headlight head-light headlamp head-lamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 15:34

## **EAST Search History**

S15 34	96	362/269.ccls. and (headlight head-light headlamp head-lamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT;	OR	ON	2007/02/27 15:36
S15 35	. 66	362/272.ccls. and (headlight head-light headlamp head-lamp)	IBM_TDB US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT;	OR	ON	2007/02/27 15:37
S15 36	59	362/286.ccls. and (headlight head-light headlamp head-lamp)	IBM_TDB US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 15:39
S15 37	139	362/287.ccls. and (headlight head-light headlamp head-lamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2007/02/27 15:42
\$15 38	47	362/418.ccls. and (headlight head-light headlamp head-lamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 15:43
S15 39	144	362/427.ccls. and (headlight head-light headlamp head-lamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR ·	ON	2007/02/27 15:46
S15 40	227	362/428.ccls. and (headlight head-light headlamp head-lamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM TDB	OR	ON	2007/02/27 15:55
S15 41	1327	362/460-468.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 15:56
S15 42	1806	((sensor sens\$4 detect\$4) same (fail\$4 faul\$4 malfunctio\$4)) and (headlight head-light headlamp head-lamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/28 08:30
\$15 43	55	S1541 and S1542	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 15:57

## **EAST Search History**

S15 44	3630	(sensor sens\$4 detect\$4) and (fail\$4 faul\$4 malfunctio\$4) and (headlight head-light headlamp head-lamp)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 16:03
S15 45	115	S1541 and S1544	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 16:02
S15 46	60	S1545 not S1543	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 16:02
S15 47	174	((sensor sens\$4 detect\$4) and (fail\$4 faul\$4 malfunctio\$4) and (headlight head-light headlamp head-lamp)).ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/28 08:25
S15 48		(valerie same molto).in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 16:06
S15 49	47	(eric same blusseau).in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/02/27 16:07
S15 50	161	(pierre same albou).in.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON <sup>.</sup>	2007/02/27 16:08
\$15 51	24	S1541 and ((sensor sens\$4 detect\$4) same (fail\$4 faul\$4 malfunctio\$4) same (headlight head-light headlamp head-lamp))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON ·	2007/02/27 16:13

2/28/07 8:58:58 AM C:\Documents and Settings\btruong\My Documents\EAST\Workspaces\SearchSave.wsp

Page 3